
For EPDM, PVC or TPO Membrane Flat Roofs


Step 5:

Apply sealant within the square flange outline.



6B:

Required Screw: #10 x 1.5" steel sheet metal screw Total number of screws required = 20 (tolerance :1/2")




Step 6A:

Place vent within the square outline & attach using a screw gun or drill.



Step 7:

Apply roofing cement over the screws and edge of flange. This is how the Aura vent should look when finished.





Active Ventilation Products, Inc. 311 First Street, Newburgh, NY 12550-4857


800-ROOF VENT (766-3836) Ph: 845-565-7770 Fax: 845-562-8963 Website: roofvents.com

Email: sales@roofvents.com

For EPDM, PVC or TPO Membrane Flat Roofs


Step 5:

Apply sealant within the square flange outline.



6B:

Required Screw: #10 x 1.5" steel sheet metal screw Total number of screws required = 20 (tolerance :1/2")




Step 6A:

Place vent within the square outline & attach using a screw gun or drill.



Step 7:

Apply roofing cement over the screws and edge of flange. This is how the Aura vent should look when finished.





Active Ventilation Products, Inc. 311 First Street, Newburgh, NY 12550-4857

800-ROOF VENT (766-3836) Ph: 845-565-7770 Fax: 845-562-8963 Website: roofvents.com

Email: sales@roofvents.com